



Since 1968

HYTORC HY-30XLCT w/ Hex Link
PRESSURE/TORQUE CONVERSION CHART

PRESSURE IN				PRESSURE IN
PSI	FT. LBS.	KGM	NM	BAR
1500	4579	633	6207	104
1600	4890	676	6626	110
1800	5513	762	7476	124
2000	6135	848	8319	138
2200	6759	935	9165	152
2400	7383	1021	10011	166
2600	8008	1108	10859	179
2800	8632	1194	11705	193
3000	9256	1280	12551	207
3200	9881	1367	13399	221
3400	10506	1453	14246	235
3600	11132	1540	15095	248
3800	11757	1626	15942	262
4000	12382	1712	16790	276
4200	13001	1798	17629	290
4400	13620	1884	18469	304
4600	14239	1969	19308	317
4800	14858	2055	20147	331
5000	15477	2140	20987	345
5200	16105	2227	21838	359
5400	16733	2314	22690	373
5600	17361	2401	23542	386
5800	17989	2488	24393	400
6000	18617	2575	25245	414
6200	19230	2660	26076	428
6400	19843	2744	26907	442
6600	20456	2829	27738	455
6800	21069	2914	28570	469
7000	21682	2999	29401	483
7200	22299	3084	30237	497
7400	22916	3169	31074	511
7600	23532	3254	31909	524
7800	24149	3340	32746	538
8000	24766	3425	33583	552
8200	25408	3514	34453	566
8400	26050	3603	35324	580
8600	26692	3692	36194	593
8800	27334	3780	37065	607
9000	27976	3869	37935	621
9200	28578	3952	38752	635
9400	28190	3899	38226	649
9600	29782	4119	40384	662
9800	30384	4202	41201	676
10000	30986	4285	42017	690

12420 TEXACO ROAD Houston, Texas 77013

713-453-6677

www.hyorctexas.com

This chart supercedes all prior version regarding this tool

03/31/2008