



Since 1968

HYTORC HY-18XLCT w/ Hex Link  
PRESSURE/TORQUE CONVERSION CHART

PRESSURE IN				PRESSURE IN
PSI	FT. LBS.	KGM	NM	BAR
1500	2676	370	3629	104
1600	2854	395	3870	110
1800	3209	444	4351	124
2000	3565	493	4834	138
2200	3922	542	5318	152
2400	4279	592	5802	166
2600	4636	641	6286	179
2800	4993	691	6771	193
3000	5350	740	7255	207
3200	5708	789	7740	221
3400	6066	839	8225	235
3600	6424	888	8711	248
3800	6782	938	9196	262
4000	7140	987	9682	276
4200	7496	1037	10165	290
4400	7852	1086	10647	304
4600	8208	1135	11130	317
4800	8564	1184	11613	331
5000	8920	1234	12096	345
5200	9277	1283	12580	359
5400	9634	1332	13064	373
5600	9991	1382	13548	386
5800	10348	1431	14032	400
6000	10705	1481	14516	414
6200	11062	1530	15000	428
6400	11419	1579	15484	442
6600	11776	1629	15968	455
6800	12133	1678	16452	469
7000	12490	1727	16936	483
7200	12848	1777	17422	497
7400	13206	1826	17907	511
7600	13564	1876	18393	524
7800	13922	1925	18878	538
8000	14280	1975	19364	552
8200	14637	2024	19848	566
8400	14994	2074	20332	580
8600	15351	2123	20816	593
8800	15708	2172	21300	607
9000	16065	2222	21784	621
9200	16421	2271	22267	635
9400	16777	2320	22750	649
9600	17133	2369	23232	662
9800	17489	2419	23715	676
10000	17845	2468	24198	690

12420 TEXACO ROAD Houston, Texas 77013 713-453-6677 www.hyorctexas.com

This chart supercedes all prior version regarding this tool

03/31/2008